

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**DE800**  
**SE**  
**> 1**  
**1.112 mi.**  
**5874 ft.**

**GARDALL SAFE**  
**219 LAMSON ST - NORTH WEST END**  
**SYRACUSE, NY 13206**

**Relative:**  
**Higher**

**Actual:**  
**432 ft.**

**Site 7 of 13 in cluster DE**

**SEMS-ARCHIVE**  
**CORRACTS**  
**RCRA-CESQG**  
**NY SHWS**  
**NY DEL SHWS**  
**NY Spills**  
**2020 COR ACTION**  
**NY MANIFEST**

**1000389168**  
**NYD002231355**

SEMS Archive:

Site ID: 0201450  
EPA ID: NYD002231355  
Cong District: 32  
FIPS Code: 36067  
FF: N  
NPL: Not on the NPL  
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information  
Latitude: +43.078432  
Longitude: -076.00

SEMS Archive Detail:

Region: 02  
Site ID: 0201450  
EPA ID: NYD002231355  
Site Name: PRESTOLITE ELECTRICAL DIVISION  
NPL: N  
FF: N  
OU: 00  
Action Code: VS  
Action Name: ARCH SITE  
SEQ: 1  
Start Date: Not reported  
Finish Date: 1980-04-01 05:00:00  
Qual: Not reported  
Current Action Lead: EPA Perf In-Hse

Region: 02  
Site ID: 0201450  
EPA ID: NYD002231355  
Site Name: PRESTOLITE ELECTRICAL DIVISION  
NPL: N  
FF: N  
OU: 00  
Action Code: PA  
Action Name: PA  
SEQ: 1  
Start Date: Not reported  
Finish Date: 1980-04-01 05:00:00  
Qual: N  
Current Action Lead: EPA Perf

Region: 02  
Site ID: 0201450  
EPA ID: NYD002231355  
Site Name: PRESTOLITE ELECTRICAL DIVISION  
NPL: N  
FF: N  
OU: 00  
Action Code: DS  
Action Name: DISCVRY

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

SEQ: 1  
Start Date: 1984-12-18 06:00:00  
Finish Date: 1984-12-18 06:00:00  
Qual: Not reported  
Current Action Lead: EPA Ovrsght

CORRACTS:

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 20130307  
Action: CA800YE  
NAICS Code(s): 336322 335312  
Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing  
Original schedule date: Not reported  
Schedule end date: Not reported

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 20130307  
Action: CA999 - Corrective Action Process Terminated  
NAICS Code(s): 336322 335312  
Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing  
Original schedule date: Not reported  
Schedule end date: Not reported

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 20110816  
Action: CA550NR  
NAICS Code(s): 336322 335312  
Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing  
Original schedule date: Not reported  
Schedule end date: Not reported

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 20110816  
Action: CA400 - Date For Remedy Selection (CM Imposed)  
NAICS Code(s): 336322 335312  
Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing  
Original schedule date: Not reported  
Schedule end date: Not reported

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 20110310  
Action: CA725YE - Current Human Exposures Under Control, Yes, Current Human  
Exposures Under Control has been verified  
NAICS Code(s): 336322 335312

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing

Original schedule date: Not reported  
Schedule end date: Not reported

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 20110310  
Action: CA750YE - Migration of Contaminated Groundwater under Control, Yes,  
Migration of Contaminated Groundwater Under Control has been verified  
NAICS Code(s): 336322 335312

Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing

Original schedule date: Not reported  
Schedule end date: Not reported

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 19970804  
Action: CA075LO - CA Prioritization, Facility or area was assigned a low  
corrective action priority  
NAICS Code(s): 336322 335312

Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing

Original schedule date: Not reported  
Schedule end date: Not reported

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 19950921  
Action: CA050 - RFA Completed  
NAICS Code(s): 336322 335312

Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing

Original schedule date: Not reported  
Schedule end date: Not reported

EPA ID: NYD002231355  
EPA Region: 2  
Area Name: SITEWIDE  
Actual Date: 19950921  
Action: CA070NO - RFA Determination Of Need For An RFI, RFI is Not Necessary  
NAICS Code(s): 336322 335312

Other Motor Vehicle Electrical and Electronic Equipment Manufacturing  
Motor and Generator Manufacturing

Original schedule date: Not reported  
Schedule end date: Not reported

RCRA-CESQG:

Date form received by agency: 01/01/2007  
Facility name: GARDALL SAFE  
Facility address: 219 LAMSON ST - NORTH WEST END

SYRACUSE, NY 13206  
EPA ID: NYD002231355  
Mailing address: PO BOX 30  
SYRACUSE, NY 13206

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Contact: STEVE THOMAS  
Contact address: PO BOX 30  
SYRACUSE, NY 13206  
Contact country: US  
Contact telephone: 315-432-9115  
Contact email: Not reported  
EPA Region: 02  
Land type: Private  
Classification: Conditionally Exempt Small Quantity Generator  
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: ELTRACORPORATION  
Owner/operator address: PO BOX 1013R  
OPERCITY, NJ 99999  
Owner/operator country: US  
Owner/operator telephone: 315-463-6621  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Operator  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Owner/operator name: EDWARD BAROODY  
Owner/operator address: PO BOX 30  
SYRACUSE, NY 13706  
Owner/operator country: US  
Owner/operator telephone: 315-432-9115  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Owner  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
Mixed waste (haz. and radioactive): No  
Recycler of hazardous waste: No  
Transporter of hazardous waste: No  
Treater, storer or disposer of HW: No  
Underground injection activity: No

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

On-site burner exemption: No  
Furnace exemption: No  
Used oil fuel burner: No  
Used oil processor: No  
Used oil refiner: No  
Used oil fuel marketer to burner: No  
Used oil Specification marketer: No  
Used oil transfer facility: No  
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006  
Site name: GARDALL SAFE  
Classification: Small Quantity Generator

Date form received by agency: 04/24/1997  
Site name: GARDALL SAFE  
Classification: Small Quantity Generator

. Waste code: D000  
. Waste name: Not Defined

. Waste code: D001  
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D006  
. Waste name: CADMIUM

. Waste code: D008  
. Waste name: LEAD

. Waste code: D018  
. Waste name: BENZENE

. Waste code: D039  
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040  
. Waste name: TRICHLOROETHYLENE

. Waste code: F002  
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003  
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

- . Waste code: U019
- . Waste name: BENZENE (I,T)
- . Waste code: U165
- . Waste name: NAPHTHALENE
- . Waste code: U188
- . Waste name: PHENOL
- . Waste code: U197
- . Waste name: P-BENZOQUINONE
- . Waste code: U226
- . Waste name: ETHANE, 1,1,1-TRICHLORO-
- . Waste code: U239
- . Waste name: BENZENE, DIMETHYL- (I,T)

Date form received by agency: 01/22/1992  
Site name: GARDALL SAFE  
Classification: Not a generator, verified

- . Waste code: NONE
- . Waste name: None

Date form received by agency: 11/19/1980  
Site name: GARDALL SAFE  
Classification: Not a generator, verified

- . Waste code: D001
- . Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
- . Waste code: F002
- . Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

- . Waste code: F003
- . Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
- . Waste code: U019
- . Waste name: BENZENE (I,T)
- . Waste code: U188
- . Waste name: PHENOL
- . Waste code: U197
- . Waste name: P-BENZOQUINONE
- . Waste code: U226
- . Waste name: ETHANE, 1,1,1-TRICHLORO-
- . Waste code: U239
- . Waste name: BENZENE, DIMETHYL- (I,T)

Corrective Action Summary:

- Event date: 09/21/1995
- Event: DETERMINATION OF NEED FOR AN INVESTIGATION-INVESTIGATION IS NOT NECESSARY
- Event date: 09/21/1995
- Event: RFA COMPLETED
- Event date: 08/04/1997
- Event: CA PRIORITIZATION-LOW CA PRIORITY
- Event date: 03/10/2011
- Event: HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
- Event date: 03/10/2011
- Event: RELEASE TO GW CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
- Event date: 08/16/2011
- Event: REMEDY DECISION
- Event date: 08/16/2011
- Event: REMEDY CONSTRUCTION-NO REMEDY CONSTRUCTED
- Event date: 03/07/2013
- Event: READY FOR ANTICIPATED USE DETERMINATION - READY FOR ANTICIPATED USE
- Event date: 03/07/2013
- Event: CA PROCESS IS TERMINATED

Facility Has Received Notices of Violations:

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Regulation violated: Not reported  
Area of violation: Used Oil - Generators  
Date violation determined: 05/16/2017  
Date achieved compliance: 05/16/2017  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL  
Enforcement action date: 05/16/2017  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: Not reported  
Area of violation: Universal Waste - Small Quantity Handlers  
Date violation determined: 04/12/2012  
Date achieved compliance: 06/06/2012  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL  
Enforcement action date: 04/13/2012  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: SR - 374  
Area of violation: Listing - General  
Date violation determined: 12/16/2005  
Date achieved compliance: 01/25/2006  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL  
Enforcement action date: 01/26/2006  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(b)(2)(i)  
Area of violation: Generators - General  
Date violation determined: 04/29/2004  
Date achieved compliance: 06/18/2004  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL  
Enforcement action date: 05/14/2004  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.9(d)(3)  
Area of violation: Generators - General  
Date violation determined: 04/29/2004



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Date achieved compliance: 06/18/2004  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL  
Enforcement action date: 05/14/2004  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(a)(8)(iii)(d)  
Area of violation: Generators - General  
Date violation determined: 04/29/2004  
Date achieved compliance: 06/18/2004  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL  
Enforcement action date: 05/14/2004  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(b)(1)  
Area of violation: Generators - General  
Date violation determined: 04/29/2004  
Date achieved compliance: 06/18/2004  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL  
Enforcement action date: 05/14/2004  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: Not reported  
Area of violation: Generators - General  
Date violation determined: 09/03/1998  
Date achieved compliance: 11/02/1998  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL  
Enforcement action date: 09/03/1998  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Regulation violated: Not reported  
Area of violation: Generators - General  
Date violation determined: 07/23/1986  
Date achieved compliance: 03/31/1988  
Violation lead agency: State  
Enforcement action: WRITTEN INFORMAL

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Enforcement action date: 07/23/1986  
Enf. disposition status: Not reported  
Enf. disp. status date: Not reported  
Enforcement lead agency: State  
Proposed penalty amount: Not reported  
Final penalty amount: Not reported  
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 05/16/2017  
Evaluation: FOCUSED COMPLIANCE INSPECTION  
Area of violation: Used Oil - Generators  
Date achieved compliance: 05/16/2017  
Evaluation lead agency: State

Evaluation date: 05/16/2017  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

Evaluation date: 04/12/2012  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Universal Waste - Small Quantity Handlers  
Date achieved compliance: 06/06/2012  
Evaluation lead agency: State

Evaluation date: 12/16/2005  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Listing - General  
Date achieved compliance: 01/25/2006  
Evaluation lead agency: State

Evaluation date: 04/29/2004  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Generators - General  
Date achieved compliance: 06/18/2004  
Evaluation lead agency: State

Evaluation date: 09/01/1998  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Generators - General  
Date achieved compliance: 11/02/1998  
Evaluation lead agency: State

Evaluation date: 03/14/1989  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

Evaluation date: 07/23/1986  
Evaluation: FINANCIAL RECORD REVIEW  
Area of violation: Generators - General  
Date achieved compliance: 03/31/1988  
Evaluation lead agency: State

Evaluation date: 06/19/1985  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

Evaluation date: 01/03/1985  
Evaluation: NON-FINANCIAL RECORD REVIEW  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

SHWS:

Program: HW  
Site Code: 57944  
Classification: N  
Region: 7  
Acres: Not reported  
HW Code: 734007  
Record Add: 11/18/1999  
Record Upd: 12/16/2003  
Updated By: kstang  
Site Description: Site has been investigated and no toxic substances could be confirmed at this site.  
Env Problem: Not reported  
Health Problem: Not reported  
Dump: Not reported  
Structure: Not reported  
Lagoon: Not reported  
Landfill: Not reported  
Pond: Not reported  
Disp Start: Not reported  
Disp Term: Not reported  
Lat/Long: Not reported  
Dell: Not reported  
Record Add: Not reported  
Record Upd: Not reported  
Updated By: Not reported  
Own Op: Not reported  
Sub Type: Not reported  
Owner Name: Not reported  
Owner Company: Not reported  
Owner Address: Not reported  
Owner Addr2: Not reported  
Owner City,St,Zip: Not reported  
Owner Country: Not reported  
HW Code: Not reported  
Waste Type: Not reported  
Waste Quantity: Not reported  
Waste Code: Not reported  
Crossref ID: Not reported  
Cross Ref Type Code: Not reported  
Cross Ref Type: Not reported  
Record Added Date: Not reported  
Record Updated: Not reported  
Updated By: Not reported

DEL SHWS:

Year: Not reported  
Site Code Id: Not reported  
Site Classification: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Region: 7  
Epa Id Number: Not reported  
Site Type - Dump: No  
Site Type - Structure: No  
Site Type - Lagoon: No  
Site Type - Landfill: No  
Site Type - Treat Pond: No  
Site Size (Acres): Not reported  
Site Size Comment: Not reported  
Period Assoc/HW Start: Not reported  
Period Assoc/HW End: Not reported  
Lat/Long: Not reported  
Lat/Long Decimal: Not reported  
Lat/Long (dms): Not reported  
Hazardous Waste Code: 734032  
Hazard Waste Disposed: Not reported  
Quantity: Not reported  
Air Data Available: No  
SW Std Contravention: No  
GW Std Contravention: No  
Soil Type: Not reported  
Sediment Data Available: No  
GW Std Contravention: No  
DW Std Contravention: No  
SW Std Contravention: No  
Air Stand Contraventions: No  
Legal Action Type: Not reported  
State Legal Action: No  
Federal Legal Action: No  
Enforce Status Code: Not reported  
Remedial Act Proposed: No  
Rem Act Under Design: No  
Rem Act In Progress: No  
Rem Act Completed: No  
Remedial Action Type: Not reported  
Soil Type: Not reported  
Depth To Groundwater: Not reported  
Owner Name: Not reported  
Owner Address: Not reported  
Owner City,St,Zip: Not reported  
  
Owner Phone: Not reported  
Owner Contact Name: Not reported  
Owner During Disposal: Not reported  
Owner During Use: Not reported  
Operator Name: Not reported  
Operator Address: Not reported  
Operator City,St,Zip: Not reported  
Operator Phone: Not reported  
Operator Contact Name: Not reported  
Oper During Disposal: Not reported  
Site Type: Not reported  
HW Disposal Period: Not reported  
Analytical Data Available: Not reported  
Applicable Std Exceeded: Not reported  
Geotech Info: Not reported  
Depth To Groundwater: Not reported  
Status: Not reported  
Nature Of Action: Not reported  
Env Prob Assessment: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Site Description:	Not reported
Confirmed HW:	Not reported
Environment Assessment:	Not reported
Health Assessment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	Not reported
NYTM Y:	Not reported
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	Exposures via drinking water are not expected because municipal water serves the area. Direct contact exposures are not expected because the site surface was capped. NYSDOH and NYSDEC will evaluate the need for additional investigations to determine the potential for soil vapor intrusion into structures on or near the site.
Description:	<p>Prestolite is no longer in operation at this location. The property was purchased by a new owner in late 1988. According to the Right-to-Know questionnaire response prepared by Prestolite, some hazardous wastes were dumped on the property in the past. Drums were observed in past inspections, but have since been removed. A PRP</p> <p>Phase II Investigation was completed in 1988. A Phase II report addendum was also submitted. Soil &amp; groundwater sampling revealed the presence of low levels of cyanide contamination. The building on site has since been cleaned and demolished, and the area has been capped. Recent resampling has revealed that cyanides in the groundwater are now below the applicable Part 703 groundwater standards. The sludge from the on-site wastewater treatment plant has been removed. Post clean-up monitoring has shown no further contamination by cyanide. Site has been satisfactorily cleaned of hazardous waste. A review of information pertaining to possible vapor intrusion is being performed during 2007 to assess the need for additional work.</p>
Record Added Date:	11/18/1999
Record Updated Date:	01/29/2008
Env Assessment:	Not reported
HW Disposed/Quantity:	Not reported
Assess/Env Prog:	Not reported
Assess/Health Prob:	Not reported
Site Description:	Not reported

SPILLS:

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Spill Number/Closed Date: 0160035 / 2001-09-12  
Facility ID: 0160035  
Facility Type: ER  
DER Facility ID: 128217  
Site ID: 150860  
DEC Region: 7  
Spill Cause: Unknown  
Spill Class: E6  
SWIS: 3400  
Spill Date: 2001-09-07  
Investigator: CFMANNES  
Referred To: Not reported  
Reported to Dept: 2001-09-10  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Institutional, Educational, Gov., Other  
Spill Notifier: Local Agency  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: 2001-09-12  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2001-09-10  
Spill Record Last Update: 2001-09-14  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: UNK  
Spiller Company: 001  
Contact Name: CHRISTOPHER SHEPHERD  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was CM "  
Remarks: "Near loading dock area there appears to be water then after a while it turns to iridescent green. This has been ongoing for about a week. There is no odor. "

All Materials:  
Site ID: 150860  
Operable Unit ID: 849908  
Operable Unit: 01  
Material ID: 527088  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

2020 COR ACTION:  
EPA ID: NYD002231355  
Region: 2  
Action: Remedy Construction

NY MANIFEST:  
Country: USA  
EPA ID: NYD002231355

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Facility Status: Not reported  
Location Address 1: 219 LAMSON ST  
Code: BP  
Location Address 2: Not reported  
Total Tanks: Not reported  
Location City: SYRACUSE  
Location State: NY  
Location Zip: 13206  
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD002231355  
Mailing Name: GARDALL SAFE  
Mailing Contact: DALE F SCHMIDT  
Mailing Address 1: P O BOX 30  
Mailing Address 2: Not reported  
Mailing City: EASTWOOD STATION  
Mailing State: NY  
Mailing Zip: 13206  
Mailing Zip 4: Not reported  
Mailing Country: USA  
Mailing Phone: 4192497723

NY MANIFEST:

Document ID: Not reported  
Manifest Status: Not reported  
seq: Not reported  
Year: 2016  
Trans1 State ID: NYD986903904  
Trans2 State ID: Not reported  
Generator Ship Date: 10/26/2016  
Trans1 Recv Date: 10/26/2016  
Trans2 Recv Date: Not reported  
TSD Site Recv Date: 11/03/2016  
Part A Recv Date: Not reported  
Part B Recv Date: Not reported  
Generator EPA ID: NYD002231355  
Trans1 EPA ID: Not reported  
Trans2 EPA ID: Not reported  
TSDF ID 1: OHD066060609  
TSDF ID 2: Not reported  
Manifest Tracking Number: 008906660FLE  
Import Indicator: N  
Export Indicator: N  
Discr Quantity Indicator: N  
Discr Type Indicator: N  
Discr Residue Indicator: N  
Discr Partial Reject Indicator: N  
Discr Full Reject Indicator: N  
Manifest Ref Number: Not reported  
Alt Facility RCRA ID: Not reported  
Alt Facility Sign Date: Not reported  
MGMT Method Type Code: H061  
Waste Code: Not reported  
Waste Code: Not reported  
Waste Code: Not reported  
Waste Code: Not reported  
Waste Code: Not reported  
Waste Code: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Quantity: 110  
Units: G - Gallons (liquids only)\* (8.3 pounds)  
Number of Containers: 2  
Container Type: DM - Metal drums, barrels  
Handling Method: B Incineration, heat recovery, burning.  
Specific Gravity: 1  
Waste Code: D001  
Waste Code 1\_2: D035  
Waste Code 1\_3: F005  
Waste Code 1\_4: D005  
Waste Code 1\_5: F003  
Waste Code 1\_6: Not reported

[Click this hyperlink](#) while viewing on your computer to access  
-1 additional NY MANIFEST: record(s) in the EDR Site Report.



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

DE836  
SE  
> 1  
1.144 mi.  
6039 ft.

PRESTOLITE  
LAMSON STREET  
SYRACUSE, NY

NY Spills

S102166199  
N/A

Site 11 of 13 in cluster DE

Relative:  
Higher

Actual:  
438 ft.

SPILLS:

Spill Number/Closed Date: 8804207 / 1988-08-12  
Facility ID: 8804207  
Facility Type: ER  
DER Facility ID: 152156

Site ID: 308319  
DEC Region: 7  
Spill Cause: Abandoned Drums  
Spill Class: Not reported  
SWIS: 3415  
Spill Date: 1988-08-11  
Investigator: GREGG  
Referred To: Not reported  
Reported to Dept: 1988-08-12  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Citizen  
Cleanup Ceased: 1988-08-12  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1988-08-15  
Spill Record Last Update: 1993-03-18  
Spiller Name: Not reported  
Spiller Company: PRESTOLITE LABS  
Spiller Address: LAMSON ST.  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was TG "

Remarks: "SIX OR SEVEN 55 GALLON DRUMS ABANDON IN PARKING AREA. SOME LABELS SAY PCB. LAB WAS CLOSED SPRING OF 88. CONCERNED THAT DRUMS ARE SITTING THERE. NO APPARENT LEAK. TURNED OVER TO SOLID WASTE."

All Materials:

Site ID: 308319  
Operable Unit ID: 919241  
Operable Unit: 01  
Material ID: 456159  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: Not reported  
Recovered: .00  
Oxygenate: Not reported